




Aplicatii suplimentare


Nr. Crt.	Model	Timp de lucru
A1	 Isometric drawing of a purple mechanical part. Dimensions include: Ø19, 38, R6, 19, 20, 13, R19, R3, 10, 40, 67, R13, 31, Ø10, 36, R19, 10, 50, 88.	2h
A2	 Isometric drawing of a blue mechanical part. Dimensions include: 45, 58, Ø55, 27.5, Ø30, 15, 14, R10, 50, 21, 41, 42.5, 100, 142, 4Ø18.	1,5h

A3




1,5h

A4




1,5h

A5




2h

A6



1,5h

A7



1,5h

A8





Figure 2


1,5h

A9




1,5h

A10




1,5h

A11




1,5h

A12




1,5h

A13





1,5h


A14



1,5h


A15	acotat en mm. 	1,5h
A16	 cote in inch, raza 0,125	1,5h

A17



1,5h


A18



2h


A19		2h
A20		2h
A21		2h

A22




1,5h

A23




2h

A24




2h

A25




A31



2h


A32




3h

A33


3h




A34

1,5h


Top view



3d view




Front view




left side view

A35




2h

A36




1.5h

A37




1,5h

A37




1,5h

A38




1,5

A39




1,5

A40



2h

A41



2h

A42

2h




Figure 2

A43

2h

